COLITU	DAVOTA	MATED	MELL	COMPLETION	DEDADT
20014	HARUIA	WAICH	AACTT	LUMPLEHUM	neruni

SOUTH DAKOTA WATER	WELL COMPLETION REPORT	07-92
Location S-F 1/4 N-W/4 Sec 19 Twp 1/6 Rg 67 County North	Well Owner: <u>Dale Oakley</u> Business Name: Address: <u>36380</u> 17474	St. Ruckham
Please mark well location with an "X"		
W	WELL LOG: FORMATION	DEPTH TO
	Yellow Clay	0 18
Well Completion Date	Blue Clay	18 115
	Shale	115 1015
6/1/03 1 Mile	Dakota	1015 1260
LOCATION: Distance from nearest potential pollution source (septic tank, abandoned well,		
feed lot, etc.)?ft. from NONE(identify source	e).	
PROPOSED USE: ☑ Domestic/Stock ☐ Municipal ☐ Business ☐ Test Holes		
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Monitoring well		
METHOD OF DRILLING:		
Myd Rutany		Feet
CASING DATA: ☐ Steel ☑ Plastic ☐ Other	If flowing: closed in pressure	
If other describe	— Controlled by ☒ Valve ☐ Reducers ☐	
PIPEWEIGHT DIAMETER FROM TO HOLE DIAMETER 200 LB/FT 5 IN 0 FT 35 FT 7/8	Heduced Flowrate	GPM
SC480 LB/FT 2 IN 25 FT 1260 FT 42		
	N WELL TEST DATA:	
GROUTING DATA	Pumped Describe:	
Grout Type No. of Sacks Grout Weight From To	1	
	•	
Describe grouting procedure	ft. AfterHrs. pump	edGPM
		edGPM
SCREEN: M Perforated pipe Manufactured	If pump installed, pump rate	GPM
Diameter 2 IN Length 220 FEI	REMARKS	RECEIVED
Material <u>PVC 2" 5ch 80</u> Slot Size <u>98</u> Set From <u>1040</u> Feet to <u>1240</u> Feet	-	
Other information		JUN - 6 2005
	This well was drilled under license #	2 PROGRAM
WAS A PACKER OR SEAL USED? YES ONO	And this report is true and accurate.	
If so, what material? Rubben	Drilling firm Stretch' Well Se	ruice Inc.
Describe packer(s) and location? above Personation	Signature of License Representative:	
DISINFECTION: Was well disinfected upon completion?	Now Grating	,
YES, How: Laboratory sent to for waterNO, Why Not?	Signature of Well Owner or Equitable Property Ho	older:
Laboratory sent to for waterNO, Why Not? quality analysisFlowing Well		
	— Date:	

'n